


Section 3: Looking Downstream from State Street Bridge
Average Water Surface



Existing Conditions



Rock Ramp Alternative & Bypass Alternative
No Change from existing



Dam Removal Alternative
Lowered 2 feet from existing


Section 2: Looking Upstream from Main Street Bridge
Average Water Surface



Existing Conditions



Rock Ramp Alternative & Bypass Alternative
No Change from existing



Dam Removal Alternative
Lowered 2 feet from existing

Section 1: Looking Downstream from E. Pleasant Street
Average Water Surface



Existing Conditions



Rock Ramp Alternative & Bypass Alternative
No Change from existing



Dam Removal Alternative
No Change from existing